



CHICAGO SILVER

5x32 R

1 3 S 1 ↻	1 3 T_{L1}^{1 1/2}	2 4 5 ① ③ ① ③ ② ④ 5 Change lead on bar 3 	2 2 4 ① ③ ③ ① ③ ③ 4 5 5 Change lead on bar 3 
R ⌈	R ⌈	④ ② ② ① ③ ① ③ ⑤ ⑤ ④ 2 places LA 	1x 3x X_L 1 ↻ to 2 4 1 5 3